

Playground Supplies limited

Unit 9, Cunliffe Drive,

Northfield Avenue Industrial Estate, Kettering,

Northants, NN16 8LD

01536 415143

Customer – Gosford & Water Eaton PC

Type of Inspection – Visual

Carried Out – Monthly

Inspected by – Terry Hawthorn

Date – 23.10.18



Inspection Details

The following inspection reports lists the defects/faults found on the date of the inspections.

Provider	Site Name	Date	Inspection Type	Inspector
Gosford & Water Eaton	Bramley Close	23.10.18	Visual	T. Hawthorn
Gosford & Water Eaton	Cromwell Close	23.10.18	Visual	T. Hawthorn

Gosford & Water Eaton PC

Site – Playground

Address – Bramley Close OX5 2GD

Inspector – T. Hawthorn

Equipment	Age Range	Sub-Type	Category	Manufacturer	Condition
Multi Play Unit	Junior	Play Equipment	Multi Play	Eibe	Good
Spring Mobile	Toddler	Play Equipment	Rocking	Eibe	Average
Mini Crawl Tunnel	Toddler	Play Equipment	Crawling	Eibe	Good
2 x Pedestrian Gates	N/A	Facilities	Perimeter	Not Known	Damaged
2 x Steel Benches	N/A	Facilities	Furniture	Not Known	Good
Steel Mounted Bin	N/A	Facilities	Furniture	Not Known	Good

Defects/Tasks – Gosford & Water Eaton PC

Unresolved Defects or Tasks – Gosford & Water Eaton PC

Equipment	Findings	Finding Date	Resolve by date	Current Status	Risk level	Cause
Surfacing	Wet Pour Shrinkage around edge causing Trip Hazards	23.01.18	ASAP	Defect	Moderate	Not Known
2 x Pedestrian gates	Require adjustment or re- fitting to allow self closing	24.08.17	ASAP	Defect	Very Low	Not Known
1 x Pedestrian gate	Missing Buffer causing pinch point	24.08.17	ASAP	Defect	Low	Wear and Tear

Gosford & Water Eaton PC

Site – Playground

Address – Cromwell Close OX5 2LW

Inspector – Terry Hawthorn

Equipment	Age Range	Sub-Type	Category	Manufacturer	Condition
See Saw	All	Play Equipment	Rocking	Wickstead	Damaged
1 bay swing with cradle seats	Toddler	Play Equipment	Swing	Wickstead	Average
1 bay swing with flat seats	Junior	Play Equipment	Swing	Wickstead	Average
Elephant Rocker	Toddler	Play Equipment	Rocking	Wickstead	Damaged
Horse Rocker	Toddler	Play Equipment	Rocking	Wickstead	Damaged
Low Level Trim Trail	All	Play Equipment	Obstacle	Wickstead	Damaged
Roundabout	All	Play Equipment	Spinning	Wickstead	Average
Multi Play Unit	Toddler	Play Equipment	Multi Play	Wickstead	Poor
Flying Spinner	Junior	Play Equipment	Spinning	Wickstead	Good
2 x Wooden Benches	N/A	Facilities	Furniture	Not Known	Average
2 x Steel Bins	N/A	Facilities	Furniture	Not Known	Damaged

Defects/Tasks – Gosford & Water Eaton PC

Unresolved Defects or Tasks – Gosford & Water Eaton PC

Equipment	Findings	Finding Date	Resolve by date	Current Status	Risk level	Cause
Steel Bins	Badly Fire Damaged	24.08.17	ASAP	Damaged	Very Low	Vandalism
See Saw	Seats split require replacing	24.08.17	ASAP	Worn	Low	Wear and Tear
Elephant Rocker	Rubber sleeve around spring split and deteriorating	24.08.17	ASAP	Worn	Low	Wear and Tear
Horse Rocker	Rubber sleeve around spring split and deteriorating	24.08.17	ASAP	Worn	Low	Wear and Tear
Low Level Trim Trail	Replace worn links on Swinging tyres	24.08.17	ASAP	Worn	Moderate	Wear and Tear
Low Level Trim Trail	Wobbly bridge missing leaving ground fixings exposed	24.08.17	ASAP	Damaged	Moderate	Not Known

Surfacing	Large gaps in rubber tile surfacing causing trip hazards across all equipment	24.08.17	ASAP	Worn	Moderate	Not Known
Multi-Play Unit	Wooden Bridge showing signs of rotting and damage	23.01.18	ASAP	Defect	Moderate	Wear and Tear

REPORT DETAILS

1. Very Low = No significant probability (Lightning strike)
2. Low = Minimal probability of occurrence. Requires significant factors to take place (Significant increase in intensity of use)
3. Moderate = Moderate probability. An added factor is needed to cause an accident. Designed use is unlikely to be problematic, additional factors required.(Cover guards loose or missing barriers at high levels)
4. High = High probability. Accident is probable without any added factors (Glass contaminant or sharp edges on equipment)
5. Very High = Very high probability. If the situation is not addressed an accident is almost certain (Severely worn chains or severely damaged surfacing with in impact area)

